




# Target Recovery


Treasure  
Hunter's  
*Supply*

1600 East State Route 73  
Waynesville, Ohio 45068  
513-897-0700 or  
Toll Free 1-855-895-5573


1. After locating a good target (metal), pinpoint the center. If your instrument has depth reading, take note of the depth. Practice on surface metals with the loop held several inches above the target.




2. Using a sturdy digging tool, preferably a trowel or knife, cut a horseshoe-shaped size plug around the pinpointed target. Leave an uncut hinge area to keep the grass in place.




3. Cut through the turf, being careful to cut around the target and not damage it.



4. Use your digging tool to pry the turf flap up and hinge it over. Your pinpointed target now rests down-side up.




5. Check for the target visually, and with your detector, to see if the target is in the flap or remains in the hole.



6. A pinpointing probe can be used to speed the process of finding the target in the flap or in the hole.




7. If additional dirt needs to be removed from the hole, place it on a drop cloth.



8. After recovering the target, the dirt can then easily be replaced with a minimum of spreading.



9. Replace the turf flap and step on it firmly. One completed, very little indication of digging should be seen.



*It is very important for the future of metal detecting that you use care in digging:*

- ▶ Check with your Dealer, Area Club, Local Police, or Parks & Recreations Department.
- ▶ Some areas may have rules on the size and type of digging tools allowed.
- ▶ Be aware of the rules, and respect the laws and restrictions in your area.
- ▶ Unightly holes are dangerous to people and livestock, and detrimental to the continued use of detectors.